

Yealink SIP Phone (T4XU & T5XW Series)

Release Notes

1. Statement

To reduce the issues from the supply chain, Yealink has developed multiple backup solutions to ensure a long-term, sustainable, and regular supply. Based on the premise of guaranteeing supplier qualification, Yealink will purchase identical quality devices from at least two different suppliers in advance.

In this release, Yealink launched WF50 in a new hardware version (V1). Therefore, Yealink upgraded T4XU and T5XW series to make them compatible with WF50 (V1).

- To be compatible with WF50 (V1), the firmware version of the T4XU series should be 108.86.0.70 or later.
- To be compatible with WF50 (V1), the firmware version of the T5XW series should be 96.86.0.70 or later.

Note: You can differentiate the new WF50 from the old one with the V1 label: the “V1” sign appears on the WF50 rear panel, the sticker of the kraft paper box and the outer box sticker.

2. Introduction

- Firmware Version:
T4XU(T42U/T43U/T46U/T48U): 108.86.0.45 upgraded to 108.86.0.70
T5XW (T53/T53W/T54W/T57W): 96.86.0.45 upgraded to 96.86.0.70
- Applicable Models: T42U, T43U, T46U, T48U, T53, T53W, T54W, T57W
- Release Date: August 25, 2022.

3. New Features

None.

4. Optimization

None.

5. Bug Fixes

None.